

Power Reactor

Event # 41142

Site: FITZPATRICK		Notification Date / Time: 10/22/2004 11:00 (EDT)	
Unit: 1	Region: 1 State : NY	Event Date / Time: 10/08/2004 18:31 (EDT)	
Reactor Type: [1] GE-4		Last Modification: 10/22/2004	
Containment Type: MARK I			
NRC Notified by: TIMOTHY PAGE		Notifications: RONALD BELLAMY R1	
HQ Ops Officer: ARLON COSTA		ANNE BOLAND R2	
Emergency Class: NON EMERGENCY		JULIO LARA R3	
10 CFR Section:		BOB DENNIG NRR	
21.21	UNSPECIFIED PARAGRAPH	VERN HODGE NRR	
		RODGER LANKSBURY R3	
		JACK WHITTEN R4	

Unit	Scram Code	RX Crit	Init Power	Initial RX Mode	Curr Power	Current RX Mode
1	N	No	0	Refueling	0	Refueling

## PART 21 REPORT: AUXILIARY RELAYS FAILURE

"In accordance with 10CFR21.21(d)(3), initial notification of a reportable defect is being made by James A. Fitzpatrick (JAF).

"The failure of two General Electric (GE) IRMA auxiliary relays in a short period of time were identified in the corrective action system as a potential common mode failure. Initial troubleshooting revealed that both relay coils indicated open. There was no evidence of any obvious cause for the coils to open circuit (e.g. discoloration, smell, physical damage). Both relays are normally de-energized relays located in a mild environment in the relay room (controlled humidity, no vibration at the panels, no local heat source that could cause accelerated aging). Both relays were installed in 1988 along with 21 other relays. A total of 33 relays were purchased from GE with the same lot/date code.

"An extent of condition review was conducted. By checking the continuity of related relay coils, two other coil failures were detected. A failure analysis of the relays was performed. The failure mode was determined to be an open in the coil due to corrosion of the coil wire. This open in the coil will prevent the relay from changing state as the relay is energized. An independent laboratory concluded that the coil insulation was damaged and that the underlying wire was damaged during coil manufacture. The damage allowed the copper wire to corrode over the years to the point of failure.

"These HMA relays were installed in multiple Emergency Core Cooling Systems (ECCS) and other systems. Each component was evaluated to determine the specific impact on the respective system. The systems affected included: Residual Heat Removal (RHR), the Low Pressure Coolant Injection (LPCI) mode of operation, Emergency Diesel Generators (EDGs), Automatic Depressurization System (ADS), Reactor Core Isolation Cooling (RCIC), Core Spray (CS), and High Pressure Coolant Injection (LPCI).

"JAFs evaluation concluded that a substantial safety hazard existed in that there was a potential for a major deficiency/major degradation of essential safety-related equipment, specifically for the RHR (LPCI) mode of

IE19

10/22/2004

U.S. Nuclear Regulatory Commission Operations Center Event Report

Page 2

Power Reactor  
operation) and HPCI systems.

Event # 41142

"No other safety functions would have been lost for the other identified systems.

"Component and Supplier:

GE HMA Type auxiliary relays

GE Part No. 12HMA124A2

GE Dwg No. DA137C6164P001

Date Code 14VC; 8836

Serial #s: D88542-0001D R02 through D88542-0033D R02

"All were purchased as safety-related from GE under JAF PO # 88-5628

"All installed safety-related relays from this lot were replaced during the recent refueling outage."

The licensee notified the NRC Resident Inspector.

\*\*\*\*\*

NRC FORM 361  
(12-2000)

# **REACTOR PLANT EVENT NOTIFICATION WORKSHEET**

U.S. NUCLEAR REGULATORY COMMISSION  
OPERATIONS CENTER

EN# 41142

NRC OPERATION TELEPHONE NUMBER: PRIMARY — 301-816-6100 or 800-532-3489\*, BACKUPS — [1st] 301-951-0550 or 800-449-3694\*,  
[2nd] 301-415-0550 and [3rd] 301-415-0553. \*Licensees who maintain their own ETS are provided these telephone numbers.

NOTIFICATION TIME <b>1100</b>	FACILITY OR ORGANIZATION <b>JAMES A. FITZPATRICK</b>	UNIT <b>1</b>	NAME OF CALLER <b>TIMOTHY PAGE</b>	CALL BACK# <b>(315) 349-6209</b>
EVENT TIME & ZONE <b>1831 EDT</b>	EVENT DATE <b>10/08/2004</b>	POWER/MODE BEFORE <b>0 % / MODE 5</b>	POWER/MODE AFTER <b>0 % / MODE 5</b>	
<b>EVENT CLASSIFICATIONS</b>		<b>1-Hr. Non-Emergency 10 CFR 50.72(b)(1)</b> (v)(A) Safe S/D Capability <b>ANA</b> (v)(B) NFR Capability <b>ANB</b> <b>4-Hr. Non-Emergency 10 CFR 50.72(b)(2)</b> (v)(C) Control of Heat Release <b>ANC</b> (v)(D) Accident Mitigation <b>AND</b> (v)(E) Offsite Mitigation <b>ANED</b> (v)(F) Loss Core VAPOR/Resp <b>ACOM</b> <b>60-Day Optional 10 CFR 50.73(a)(1)</b> Invalid Specified System Activation <b>ANV</b> Other Unspecified Requirement (Identify) <b>✓ 10CFR21.21(d)(3) <b>NONR</b></b> <b>NONR</b>		
GENERAL EMERGENCY GEN/AEC	TS Deviation ADEV			
SITE AREA EMERGENCY SIT/AEC	4-Hr. Non-Emergency 10 CFR 50.72(b)(2)			
ALERT ALE/AEC	(i) TS Required S/D ASHU			
UNUSUAL EVENT UNL/AEC	(iv)(A) ECCS Discharge to RCS ACCB			
50.72 NON-EMERGENCY (see next column)	(iv)(B) RPS Actuation (scram) ARPS			
PHYSICAL SECURITY (73.71) DDD	(d) Offsite Notification AFRE			
MATERIAL EXPOSURE ETT	8-Hr. Non-Emergency 10 CFR 50.72(b)(3)			
FITNESS FOR DUTY FRT	(ii)(A) Degraded Condition ADEG			
OTHER UNSPECIFIED RECMT. (see last column)	(ii)(B) Unanalyzed Condition AUNA			
INFORMATION ONLY INF	(iv)(A) Specified System Actuation AESF			

**DESCRIPTION**

Include: Systems affected, actuations and their initiating signals, causes, effect of event on plant, actions taken or planned, etc. (Continue on back)

In accordance with 10CFR21.21(d)(3), initial notification of a reportable defect is being made by James A. FitzPatrick (JAF).

The failure of two General Electric (GE) HMA auxiliary relays in a short period of time were identified in the corrective action system as a potential common mode failure. Initial troubleshooting revealed that both relay coils indicated open. There was no evidence of any obvious cause for the coils to open circuit (e.g. discoloration, smell, physical damage). Both relays are normally de-energized relays located in a mild environment in the relay room (controlled humidity, no vibration at the panels, no local heat source that could cause accelerated aging). Both relays were installed in 1988 along with 21 other relays. A total of 33 relays were purchased from GE with the same lot/date code.

An extent of condition review was conducted. By checking the continuity of related relay coils, two other coil failures were detected. A failure analysis of the relays was performed. The failure mode was determined to be an open in the coil due to corrosion of the coil wire. This open in the coil will prevent the relay from changing state as the relay is energized. An independent laboratory concluded that the coil insulation was damaged and that the underlying wire was damaged during coil manufacture. The damage allowed the copper wire to corrode over the years to the point of failure.

(continued)

NOTIFICATIONS	YES	NO	WILL BE	ANYTHING UNUSUAL OR NOT UNDERSTOOD?	<input type="checkbox"/> YES (Explain above)	<input checked="" type="checkbox"/> NO
NRC RESIDENT	✓					
STATE(s)		✓		DID ALL SYSTEMS FUNCTION AS REQUIRED?	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO (Explain above)
LOCAL		✓				
OTHER GOV AGENCIES		✓		MODE OF OPERATION UNTIL CORRECTED: <b>MODE 5</b>	ESTIMATED RESTART DATE: <b>N/A</b>	ADDITIONAL INFO ON BACK
MEDIA/PRESS RELEASE		✓				<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

NRC FORM 361 (12-2000)

## ADDITIONAL INFORMATION

PAGE 2 OF 2

RADIOLOGICAL RELEASES: CHECK OR FILL IN APPLICABLE ITEMS (specific details/explanations should be covered in event description)					
LIQUID RELEASE	GASEOUS RELEASE	UNPLANNED RELEASE	PLANNED RELEASE	ONGOING	TERMINATED
MONITORED	UNMONITORED	OFFSITE RELEASE	T. S. EXCEEDED	RM ALARMS	AREAS EVACUATED
PERSONNEL EXPOSED OR CONTAMINATED		OFFSITE PROTECTIVE ACTIONS RECOMMENDED		*State release path in description	
	Release Rate (Ci/sec)	% T. S. LIMIT	HOO GUIDE	Total Activity (Ci)	% T. S. LIMIT
Noble Gas			0.1 Ci/sec		1000 Ci
Iodine			10 uCi/sec		0.01 Ci
Particulate			1 uCi/sec		1 mCi
Liquid (excluding tritium and dissolved noble gases)			10 uCi/min		0.1 Ci
Liquid (tritium)			0.2 Ci/min		5 Ci
Total Activity					
	PLANT STACK	CONDENSER/AIR EJECTOR	MAIN STEAM LINE	SG BLOWDOWN	OTHER
RAD MONITOR READINGS					
ALARM SETPOINTS					
% T. S. LIMIT (if applicable)					
RCS OR SG TUBE LEAKS: CHECK OR FILL IN APPLICABLE ITEMS: (specific details/explanations should be covered in event description)					
LOCATION OF THE LEAK (e.g., SG #, valve, pipe, etc.)					
LEAK RATE	UNITS: gpm/gpd	T. S. LIMITS	SUDDEN OR LONG-TERM DEVELOPMENT		
LEAK START DATE	TIME	COOLANT ACTIVITY AND UNITS:	PRIMARY	SECONDARY	
LIST OF SAFETY RELATED EQUIPMENT NOT OPERATIONAL					

## EVENT DESCRIPTION (Continued from front)

These HMA relays were installed in multiple Emergency Core Cooling Systems (ECCS) and other systems. Each component was evaluated to determine the specific impact on the respective system. The systems affected included: Residual Heat Removal (RHR) (the Low Pressure Coolant Injection (LPCI) mode of operation), Emergency Diesel Generators (EDGs), Automatic Depressurization System (ADS), Reactor Core Isolation Cooling (RCIC), Core Spray (CS), and High Pressure Coolant Injection (HPCI).

JAFs evaluation concluded that a substantial safety hazard existed in that there was a potential for a major deficiency/major degradation of essential safety-related equipment, specifically for the RHR (LPCI mode of operation) and HPCI systems.

No other safety functions would have been lost for the other identified systems.

## Component and Supplier:

GE HMA Type auxiliary relays

GE Part No. 12HMA124A2

GE Dwg No. DA137C6164P001

Date Code 14VC; 8836

Serial #s: D88542-0001D R02 through D88542-0033D R02

All were purchased as safety-related from GE under JAF PO # 88-5628

General Electric Nuclear Energy

M/C 397

175 Curtner Ave.

San Jose, CA 95125

All installed safety-related relays from this lot were replaced during the recent refueling outage.